# Making WinPE USB Disk SOP

1. **Prepare a clean USB drive, size less than 32GB**
2. **Open File Explore. Mouse right click your USB Drive then select Format**

3. **File System select FAT32 (Default) then press Start**

4. **Unzip WinPE_USBDisk_V2.zip and copy all files into your USB drive root folder.**

5. **Plug your USB Drive into USB port.**

6. **Hold ESC key then press power button to enter Boot Menu. Select your USB drive and press enter key to boot.**
   For detail steps reference FAQ : [Notebook/Desktop/AIO] How to boot the system from USB flash drive/CD-ROM | Official Support | ASUS Global

7. If your Drive C have been locked by BitLocker, need enter BitLocker Recovery key to unlock BitLocker temporary.

   How to get BitLocker Recovery key reference FAQ

   [Notebook/Desktop/AIO] Troubleshooting - How to fix it shows BitLocker recovery screen after power on/Find BitLocker recovery key | Official Support | ASUS Global

8. If you enter correct BitLocker Recovery key or without BitLocker, wait process finished and It will show PASS result.

9. Remove your USB Drive then press any key to continue and reboot system automatically.