



# Making WinPE USB Disk SOP


1. Prepare a USB drive with a minimum capacity of 4GB and a maximum capacity of 32GB.
2. Open File Explorer. Right-click your USB Drive then select Format.



3. In the File System, select FAT32 (Default), then press Start.




#### 4. Unzip WinPE\_USBDisk.zip and copy all files into your USB drive root folder.



#### 5. Plug your USB Drive into a USB port.

#### 6. Hold the ESC key, then press the power button to enter Boot Menu. Select your USB drive and press the Enter key to boot.


For detail steps reference FAQ : [\[Notebook/Desktop/AIO\] How to boot the system from USB flash drive/CD-ROM | Official Support | ASUS Global](#)




7. If your Drive C has been locked by BitLocker, you need to enter the BitLocker Recovery key to unlock BitLocker temporarily.

For how to get the BitLocker Recovery key, refer to the FAQ:

[\[Notebook/Desktop/AIO\] Troubleshooting - How to fix it shows BitLocker recovery screen after power on/Find BitLocker recovery key | Official Support | ASUS Global](#)



8. If you enter the correct BitLocker Recovery key or there is no BitLocker, wait for the process to finish and it will show a PASS result.



9. Remove your USB Drive then press any key to continue and reboot the system automatically.